L Number	Hits	Search Text	DB	Time stamp
1	271	(seat\$5 near4 (tens\$5 stress strai force load) near3	USPAT;	2004/09/15 15:06
		(test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5	EPO; JPO	
		determin\$5 measur\$5 transducer cell meter gauge		
		monitor\$5)).clm.		
2	31	((seat\$5 near4 (tens\$5 stress strai force load)	USPAT;	2004/09/15 16:10
		near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5	EPO; JPO	
		determin\$5 measur\$5 transducer cell meter gauge	•	
		monitor\$5)).clm.) and (strain near3 gauge).clm.		
3	5	(((seat\$5 near4 (tens\$5 stress strai force load)	USPAT:	2004/09/15 15:27
	_	near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5	EPO; JPO	
		determin\$5 measur\$5 transducer cell meter gauge		
		monitor\$5)).clm.) and (strain near3 gauge).clm.)		
		and (cpu computer process\$5).clm.		
13	81	((seatbelt (seat near2 belt)) near4 (tens\$5 stress	USPAT;	2004/09/15 16:10
	0.	strain force load) near3 (test\$5 detect\$5 sens\$5	EPO; JPO	200-7700710 10:10
		estimat\$5 evalut\$5 determin\$5 measur\$5	2.0,0.0	
		transducer cell meter gauge monitor\$5)).clm.		
16	2	((((seatbelt (seat near2 belt)) near4 (tens\$5 stress	USPAT;	2004/09/15 15:39
		strain force load) near3 (test\$5 detect\$5 sens\$5	EPO; JPO	2007/09/10 10.09
		estimat\$5 evalut\$5 determin\$5 measur\$5	LFO, 0FO	
		transducer cell meter gauge monitor\$5)).clm.) and		,
		(strain near3 gauge).clm.) and (cpu computer		
		\$6process\$5).clm.		
	5		LICDAT.	2004/09/15 16:13
	5	((((USPAT;	2004/09/15 16:13
		strain force load) near3 (test\$5 detect\$5 sens\$5	EPO; JPO	:
		estimat\$5 evalut\$5 determin\$5 measur\$5		
		transducer cell meter gauge monitor\$5)).clm.) and		
		(strain near3 gauge).clm.) and (cpu computer		
47	•	\$6process\$5)		0004/00/45 45 45
17	1	("6231076").PN.	USPAT;	2004/09/15 15:45
			EPO; JPO	
14	11	(((seatbelt (seat near2 belt)) near4 (tens\$5 stress	USPAT;	2004/09/15 15:49
		strain force load) near3 (test\$5 detect\$5 sens\$5	EPO; JPO	
		estimat\$5 evalut\$5 determin\$5 measur\$5	1	
	,	transducer cell meter gauge monitor\$5)).clm.) and		
		(strain near3 gauge).clm.		
18	17		USPAT;	2004/09/15 15:49
		strain force load) near3 (test\$5 detect\$5 sens\$5	EPO; JPO	
		estimat\$5 evalut\$5 determin\$5 measur\$5		
		transducer cell meter gauge monitor\$5)).clm.) and		
		(strain near3 gauge)		
19	326	((belt) near4 (tens\$5 stress strain force load) near3	USPAT;	2004/09/15 16:11
		(test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5	EPO; JPO	
		determin\$5 measur\$5 transducer cell meter gauge		
		monitor\$5)).clm.		
20	21	(((belt) near4 (tens\$5 stress strain force load)	USPAT;	2004/09/15 16:12
		near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5	EPO; JPO	
		determin\$5 measur\$5 transducer cell meter gauge		
		monitor\$5)).clm.) and (strain near3 gauge).clm.		
21	1254078	"21" and (cpu computer \$6process\$5)	USPAT;	2004/09/15 17:27
			EPO; JPO	
22	13	((((belt) near4 (tens\$5 stress strain force load)	USPAT;	2004/09/15 17:29
		near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5	EPO; JPO	
		determin\$5 measur\$5 transducer cell meter gauge		
		monitor\$5)).clm.) and (strain near3 gauge).clm.)		
		and (cpu computer \$6process\$5)		